

Cinder pits

<u>Number</u> (1)	<u>Type of Material</u> (2)	<u>Quantity</u> (3)	<u>Access</u> (5)	<u>Owner</u> (6)
25-11-14-1F	Cinders	-	2516	-
25-11-34-1F	Cinders	-	2516	-
26-13-17-1F		-	2629	-
26-13-28-1P	Basalt Rock	-	Hwy.31	Oregon State
26-13-7-1F	Cinders	-	2629	-
27-12-6-1F	Cinders	-	2516	-
27-12-18-1F		-	2726	-
27-12-20-1F	Cinder Pit	-	2516	-
27-13-18-1F	Cinder Pit	-	2623	-
28-11-24-1P	Cinder Pit	-	2415	Weyerhaeuser
28-11-28-1F	Cinders	-	283	-
28-11-30-1	Crusher Pit	-	2727	-
28-14-17-State	Gravel	-	Hwy.31	State
28-12-1-1F	Cinder Pit	-	278	-
28-12-30-1F	Cinder Pit	20M+C.Y.	2895	-
28-12-12-1F	Cinder Pit	-	278	-
28-14-24-1P	Gravel	-	Hwy.31	State
29-11-2-1P	Cinder Pit	-	2878	Weyerhaeuser
29-12-3-1F	Cinder Pit	-	2800	-
29-12-12-1F	Pit run base	-	2800	-
29-12-17&20-1R&P	Cinder Pit	-	2973A	F.S. & Weyerhaeuser
29-12-28-1	Cinders	10M+C.Y.	2970	-
29-12-32-1F	Cinder Pit	20M+C.Y.	2970	-
29-12-32-2F	Cinder Pit	20M+C.Y.	2970	-
29-14-22-1F	Cinder Pit	400M+C.Y.	2917	-
29-14-30-1F	Cinder Pit	50M+C.Y.	2916	-
29-15-33	Possible Cinder		2914	-
29-16-34-1	Cinder Pit	20-30M C.Y.	290	-
30-12-2-1F	Cinders	25M+C.Y.	2971	-
30-12-3-1F	Cinder Pit	20M+C.Y.	2971	-
30-12-14-1F	Cinder Pit	50M+C.Y.	3040	-
29-12-32-1F	Cinder Pit	20M C.Y.	2970	-
30-12-34-1F	Cinders	100M C.Y.	2912	-
30-13-1-1F	Obsidian	30M C.Y.	2913	-

<u>Number</u> (1)	<u>Type of Material</u> (2)	<u>Quantity</u> (3)	<u>Access</u> (5)	<u>Owner</u> (6)
30-13-24-1F	Cinder Pit	50M C.Y.	3021	--
30-14-2-1F	Obsidian		2902	--
30-14-9-1F	Cinder Pit	100M C.Y.	3010-2823	--
30-14-27-1F	Cinder Pit	500M C.Y.	2823	--
30-15-18-1P	Cinder Pit		3035	Weyerhaeuser
30-16-3-1	Loose 1"-0" & Basalt	100M C.Y.	290	--
30-16-9-1F	Rock	20M+C.Y.	290	--
31-12-1-1F	Cinders		3142B	--
30-16-16-1P	Cinders	100M+C.Y.	3036C	Weyerhaeuser
31-12-13-1P				Weyerhaeuser
31-13-2-1F	Shale quarry		3038	--
31-13-12-1F	Cinder Pit	500M+C.Y.	30038	--
31-13-34-1F	Obsidian		30038	--
31-14-10-1F	Cinder Pit	500M+C.Y.	2913	--
31-14-18-1F	Assumed Cinders	--	31048	--
31-14-24-1F	Cinder Pit	--	3120	--
31-15-4-1P	Cinder Pit	200M C.Y.	3038F	Weyerhaeuser
31-15-29-1F	Cinder Pit	500M+C.Y.	3012	--
31-15-29-2F	Cinder Pit		3006	--
31-15-30-1F	Cinders	20M C.Y.	3012C	--

State Department of Geology and Mineral Industries

702 Woodlark Building
Portland 5, Oregon

BUCKEYE BUTTE CINDERS

Klamath County

Volcanic cinders from Buckeye Butte have been used for road metal by the State Highway Department. The butte lies 3 miles west of U. S. Highway 97 at a point about 3 miles south of Beaver Marsh in north central Klamath County. Legal description is sec. 3, T. 29 S., R. 7 E.

Informant: Don C. Birch

Report by: R. S. Mason
2-11-52

State Department of Geology and Mineral Industries

702 Woodlark Building
Portland 5, Oregon

CRESCENT BUTTE CINDERS

Klamath County

Cinders from Crescent Butte have been used by the State Highway Department for road ballast. The butte lies about $1\frac{1}{2}$ miles east of the town of Crescent which is on Highway 97 about 1 mile south of Gilchrest in northeastern Klamath County.

28(?) - 245-9E

Informant: Don C. Birch

Report by: R. S. Mason
2-11-52